

# STERILIZATION OF VOLARA

The sterilization of Volara by Ethylene Oxide is not recommended. The combination of temperature and vacuum has occasionally demonstrated dramatic shrinkage in this material.

When sterilization is required, radiation sterilization is recommended.

**Marketing Bulletin 6**

May, 2009

Because we cannot anticipate or control the many different conditions under which this information and our products may be used, we do not guarantee the applicability of the accuracy of this information or the suitability of our products in any given situation. Users of our products should make their own tests to determine the suitability of each product for their particular purposes. The products discussed are sold without warranty, either expressed or implied, and buyer assumes all responsibility for loss or damage arising from the handling and use of our products, whether done in accordance with directions or not. Also, statements concerning the possible use of our products are not intended as recommendations to use our products in the infringement of any patent.

**SEKISUI**



[www.SekisuiVoltek.com](http://www.SekisuiVoltek.com)

100 Shepard Street, Lawrence, MA 01843-1089 800.225.0668 • 978.685.2557 • Fax 978.685.9861